

Viscosity *	300 - 320 cps
Injection Temperature	155 - 160°F / 68-71°C
Softening Point	68.4° F / 20.2°C
Ash Content	<0.001%
Penetration**	3 - 15 dmm
Shrinkage	<1.0%
Specific Gravity	0.8555

<sup>\*</sup> Viscosity is a measure of a liquid's fluidity — how easily it flows.

Here is a helpful comparison guide for evaluating the numbers above:

Water	Maple Syrup150	Molasses
Blood	Castor Oil250	Chocolate Syrup10,000
Anti-Freeze15	Glycerin	Ketchup50,000
Corn Oil	Honey	

<sup>\*\*</sup> Penetration is a measure of how hard or soft a wax is. It measures the distance a needle point will penetrate a sample under standard conditions.